



DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

**WAGON
VIBRATOR
NO. 1**

WARNING TAG
ISOLATION TAG

DANGER

**ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD**

MACKEY STICKERS & SIGNS 4988 5655

WAGON
VIBRATOR
NO. 1


OIR Disclosure Log

J. & P. RICHARDSON INDUSTRIES PTY. LTD.
A.B.N. 23 001 952 325
114 CAMPBELL AVENUE, WAGOL, BRISBANE, QLD. 4072
Phone: (07) 3271 2911 - All Hours Fax: (07) 3271 3600
ELECTRICAL CONTRACTORS & ENGINEERS
INDUSTRIAL - COMMERCIAL - MINING
Web: www.jpri.com.au Ref: 08/011

DS01-WAGON VIBRATOR WV1
PNEUMATIC CUBICLE

OIR Disclosure Log


PANEL ISOLATOR
JS1 AIR MV02




WARNING
This Equipment
HAS NOT BEEN
IDENTIFIED AS
BEING CORRECTLY
ISOLATED AND
CHECKED AND
AUTHORISED BY AN
AUTHORISED
ISOLATOR



AIR DISCONNECT













DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

**WAGON
VIBRATOR
NO. 2**



DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

**WAGON
VIBRATOR
NO. 2**



DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

WAGON
VIBRATOR
NO. 2

DocuSure Log

DANGER

ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

WAGON
VIBRATOR
NO. 2





WASOM
VIBRATOR
NO. 2

Disposal Log

DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

**WAGON
VIBRATOR
NO. 2**

TM5 B.C.ISOL

TRAVEL
150 mm

DANGER
ISOLATE EQUIPMENT
BEFORE
REMOVING GUARD

**WAGON
VIBRATOR
NO. 2**



**WAGON
VIBRATOR
NO. 2**

OIR Disclosure Log

**WAGON
VIBRATOR
NO. 2**

OIR Disclosure Log

J. & P. RICHARDSON INDUSTRIES PTY. LTD.

A.B.N. 23 001 952 325



114 CAMPBELL AVENUE, WACOL, BRISBANE, QLD. 4076

Phone: (07) 3271 2911 - All Hours Fax: (07) 3271 3623

ELECTRICAL CONTRACTORS & ENGINEERS

INDUSTRIAL - COMMERCIAL - MINING

Web: www.jpr.com.au

Ref: 02-06-857411

TIER 2

DS01-SUBSTATION No.1
WAGON VIBRATOR WV1

MAIN ISOLATOR



WARNING
 Undefined Arc Flash Hazard
 Present When Covers Removed
 "Refer to procedure, 'Line Working' for all Line Electrical Equipment" prior to performing the work.
 Controlled Document No. NP-FWTC-400026

PPE REQUIRED		
Clothing	As Determined By JSA	
Head/Ear/Feet/Hand	As Determined By JSA	
Hand/Tool/Other	As Determined By JSA	
Flash Protection Boundary	1000 AC	Undefined Energy
Clearance	1000 AC	Undefined

Warning: No Arc Flash Category Determination Possible

WARNING
 Undefined Arc Flash Hazard
 Present When Covers Removed
 "Refer to procedure, 'Line Working' for all Line Electrical Equipment" prior to performing the work.
 Controlled Document No. NP-FWTC-400026

PPE REQUIRED		
Clothing	As Determined By JSA	
Head/Ear/Feet/Hand	As Determined By JSA	
Hand/Tool/Other	As Determined By JSA	
Flash Protection Boundary	1000 AC	Undefined Energy
Clearance	1000 AC	Undefined

Warning: No Arc Flash Category Determination Possible

DC POWER ISOLATOR



OIR Disclosure Log



Section 47(3)(b)

OIR Disclosure Log